


ULINE H-2623

3M® H-150 SCOTCH™ LOW NOISE DISPENSER

1-800-295-5510
uline.com



OPERATION

LOADING

1. Pull back spring-loaded pressure bar with thumb and clamp tape roll to rotating shaft. (See Figure 1)
2. With adhesive side down, thread tape between metal guide and roller. (See Figure 2)
3. Pull tape towards you. Tear off any excess tape. Now you are ready for dispensing. (See Figure 3)
4. Confirm proper tape path. (See Figure 4)

OPERATING

1. Start on side of box, roll tape applicator over corner of box, centered on top seam. (See Figure 5)
2. Pull dispenser across box top seam, applying pressure to applicator roller to obtain a tight seal.

