














ULINE H-4521

DELUXE MESH CHAIR

1-800-295-5510
uline.com


Para Español, vea página 2.
Pour le français, consulter la page 3.

PARTS LIST


| | | | | | |
|---|--------------------------|---|------------------------|---|---------------------------|
| 1 | Caster x 5 | 2 | 5-Star Base x 1 | 3 | Gas Lift x 1 |
|  | |  | |  | |
| 4 | Mechanism x 1 | 5 | Seat Cushion x 1 | 6 | Back Cushion x 1 |
|  | |  | |  | |
| 7 | Armrest x 2 | 8 | Hand Grip x 2 | 9 | Allen Wrench x 1 |
|  | |  | |  | |
| 10 | Screw x 3 5/16 x 3/4" | 11 | Screw x 4 5/16 x 1" | 12 | Screw x 2 1/4 x 1 1/2" |
|  | |  | |  | |
| | | | | 13 | Screw x 4 1/4 x 1 1/4" |
| | | | |  | |

ASSEMBLY INSTRUCTIONS


Step 1




Step 2




Step 3




Step 4



Step 5


















ULINE H-4521







SILLA DE MALLA DE ALTA CALIDAD

800-295-5510
uline.mx

LISTA DE PARTES

| | | | | | | | |
|---|---|---|---|---|--|---|--|
| 1 | 5 Ruedas | 2 | 1 Base Estrella | 3 | 1 Pistón de Aire | | |
|  | |  | |  | | | |
| 4 | 1 Mecanismo | 5 | 1 Asiento | 6 | 1 Respaldo | | |
|  | |  | |  | | | |
| 7 | 2 Descansabrazos | 8 | 2 Asas | 9 | 1 Llave Allen | | |
|  | |  | |  | | | |
| 10 | 3 Tornillos 7.9 x 19 mm (5/16 x 3/4") | 11 | 4 Tornillos 7.9 x 25.4 mm (5/16 x 1") | 12 | 2 Tornillos 6.4 x 38.1 mm (1/4 x 1 1/2") | 13 | 4 Tornillos 6.4 x 44.5 mm (1/4 x 1 3/4") |
|  | |  | |  | |  | |

INSTRUCCIONES DE ENSAMBLE














| | | |
|---|--|---|
| <p>Paso 1</p>  | <p>Paso 2</p>  | <p>Paso 3</p>  |
| <p>Paso 4</p>  | <p>Paso 5</p>  |  |

ULINE H-4521







CHAISE DE LUXE EN MAILLE

1-800-295-5510
uline.ca

LISTE DES PIÈCES

| | | | | | |
|---|---|---|---|---|--|
| 1 | Roulette x 5 | 2 | Étoile à 5 branches x 1 | 3 | Vérin pneumatique x 1 |
|  | |  | |  | |
| 4 | Mécanisme x 1 | 5 | Siège x 1 | 6 | Dossier x 1 |
|  | |  | |  | |
| 7 | Accoudoir x 2 | 8 | Poignée de commande x 2 | 9 | Clé Allen x 1 |
|  | |  | |  | |
| 10 | Vis x 3 7,9 x 19 mm (5/16 x 3/4 po) | 11 | Vis x 4 7,9 x 25,4 mm (5/16 x 1 po) | 12 | Vis x 2 6,4 x 38,1 mm (1/4 x 1 1/2 po) |
|  | |  | |  | |
| | | | | 13 | Vis x 4 6,4 x 44,5 mm (1/4 x 1 3/4 po) |
| | | | |  | |

INSTRUCTIONS D'ASSEMBLAGE

| | | |
|--|--|--|
| <p>Étape 1</p>  <p>Diagram showing the 5-spoke star base (2) with casters (1) being attached to the bottom of each spoke.</p> | <p>Étape 2</p>  <p>Diagram showing the seat (5) being attached to the star base (2) using screws (12) and the pneumatic cylinder (3).</p> | <p>Étape 3</p>  <p>Diagram showing the backrest (6) being attached to the seat (5) using screws (11) and the control lever (8).</p> |
| <p>Étape 4</p>  <p>Diagram showing the armrests (7) being attached to the seat (5) using screws (10) and the control lever (8).</p> | <p>Étape 5</p>  <p>Diagram showing the backrest (6) being attached to the base (2) using screws (13).</p> |  <p>Final assembly diagram showing the completed chair with all parts (1-13) in place.</p> |