

ULINE H-915 INDUSTRIAL HEAT GUN

1-800-295-5510
uline.com



TROUBLESHOOTING

| OPERATING ISSUE | RECOMMENDATIONS |
|-------------------------------|---|
| Gun is not turning on. | If the gun has been used recently the internal thermostat may be keeping the gun from turning on. Allow the gun to cool for 20-30 minutes and try again. |
| Gun is blowing only cool air. | Adjust the dial on the back of the unit. |

ULINE H-915
PISTOLA DE CALOR
INDUSTRIAL

800-295-5510
uline.mx



SOLUCIÓN DE PROBLEMAS

| PROBLEMA DE FUNCIONAMIENTO | RECOMENDACIONES |
|----------------------------------|--|
| La pistola no enciende. | Si la pistola se ha usado recientemente, puede que el termostato interno esté evitando que la pistola encienda. Deje que la pistola se enfríe entre 20-30 minutos e inténtelo de nuevo. |
| La pistola solo emite aire frío. | Ajuste el disco ubicado en la parte posterior de la unidad. |

ULINE H-915
PISTOLET THERMIQUE
INDUSTRIEL

1-800-295-5510
uline.ca



DÉPANNAGE

| PROBLÈME | RECOMMANDATIONS |
|--|---|
| Le pistolet ne s'allume pas. | Si le pistolet a récemment été utilisé, le thermostat interne peut empêcher le pistolet de s'allumer. Laissez le pistolet refroidir pendant 20 à 30 minutes, puis réessayez. |
| Le pistolet ne souffle que de l'air frais. | Réglez la molette à l'arrière de l'appareil. |