Service Information	
PDD Contact : David Arbeit Test or Eva	raluation : Test Report Number : 25642
Received Date : 12/23/2008 Processed	d Date : 12/26/2008 GroundExpress
Customer Information	FedEx Location Information
Acct # : 221033531	Express Station ID: FEPA
Uline	Express Sr Manager: Stephen Strong
2200 S. Lakeside Dr.	Ground Terminal Id: WHLG
Waukegan, IL 60085 USA	Ground Sr Manager: Scott Haeger
Contact: Maryane Semenyuk	Sales Professional : Suzanne M. Brody
Phone: 847-473-3000	Phone Number : 815-302-3190
	Field Engineer: Scott A. Gindt
	Phone Number : 414-443-2078
Product Information	
Commodity Code: 58 UN No:	Model Number: S-6715 Pcs. Per Pkg: 3
	Wine Bottle Shipper -
-	
Packaging Information	
Size : L (in): 15 W (in): 4.75 H(in): 15.25 Wt (I	(Ib): 9.45 Outer Container Type: Corrugated
Container Specs: C-Flute Single Wall 200 Burst Test	t
Other Outer Info: Regular slotted container	
Inner Packaging I: Inner Pac	ckaging II: Polystyrene Fo Sealing Method: Tape
Other Inner Info: 2-piece custom polystyrene foam	
Test Procedures Completed	
Test Type : International - FedEx	
Drop Height (in) : 30 inches	Drop Sequence : Two Sets Free - Fall
Drop Results: No Visible Damage	
Compression Factor: 5	Compression Load (lbf) : 231
Compression Results: Meets Minimum Specifications	
Compression Results: Meets Minimum Specifications Vibration Profile: International FedEx	Vibration Duration: 90 Minutes Random
•	Vibration Duration: 90 Minutes Random
Vibration Profile: International FedEx	Vibration Duration: 90 Minutes Random Impact Velocity (ft/s):
Vibration Profile:International FedExVibration Results:No Visible Damage	

<u>25642</u>

Test Results Date: 12/29/2008

Passed	A Package,with article, that has passed all the Fedex Standard Testing Procedures. For Commodiities restricted under Liabilities Not Assumed in the Fedex Service Guide, Service Guide Terms and Conditions will take precedence.
ailed:	A package, with article, that has failed all FedEx Standard Testing Procedures.
Pending:	A package, with article, that has been tested to all FedEx Standard Test Procedures. Confirmation of results is subject to customer inspection.

Comments and Packaging Recommendations*

* Our provision of advice, assistance or guidance on the appropriate packaging of shipment does not constitute acceptance of liability, unless such advice, assistance or guidance is in writing from the FedEx Packaging Design and Development department and expressly accepts liability in the event of a damaged shipment.

Photos / Drawings (if Applicable)











