

Service Information

PDD Contact : David Arbeit **Test or Evaluation :** Test **Report Number :** 25643
Received Date : 12/23/2008 **Processed Date :** 12/26/2008 **GroundExpress**

Customer Information

Acct # : 221033531
Uline
2200 S. Lakeside Dr.
Waukegan, IL 60085 USA
Contact: Maryane Semenyuk
Phone: 847-473-3000

FedEx Location Information

Express Station ID: FEPA
Express Sr Manager: Stephen Strong
Ground Terminal Id: WHLG
Ground Sr Manager: Scott Haeger
Sales Professional : Suzanne M. Brody
Phone Number : 815-302-3190
Field Engineer: Scott A. Gindt
Phone Number : 414-443-2078

Product Information

Commodity Code : 58 **UN No :** **Model Number:** S-6716 **Pcs. Per Pkg:** 6
Values : \$35.00 **Product Description:** 6 Wine Bottle Shipper -

Packaging Information

Size : L(in): 13 **W (in):** 9.25 **H(in):** 16 **Wt (lb):** 18.15 **Outer Container Type:** Corrugated
Container Specs: C-Flute Single Wall 200 Burst Test
Other Outer Info: Regular slotted container
Inner Packaging I: **Inner Packaging II:** Polystyrene Fo **Sealing Method:** Tape
Other Inner Info: 2-piece custom polystyrene foam.

Test Procedures Completed

Test Type : International - FedEx
Drop Height (in) : 30 inches **Drop Sequence :** Two Sets Free - Fall
Drop Results: No Visible Damage
Compression Factor: 5 **Compression Load (lbf) :** 387
Compression Results: Meets Minimum Specifications
Vibration Profile: International FedEx **Vibration Duration:** 90 Minutes Random
Vibration Results: No Visible Damage
Impact Sequence: **Impact Velocity (ft/s):**
Impact Results:
Other Applicable Tests: **Results:**

Test Results

Result:	Passed	Date:	12/29/2008
----------------	--------	--------------	------------

Definitions of Results

Passed	A Package,with article, that has passed all the Fedex Standard Testing Procedures. For Commodiities restricted under Liabilities Not Assumed in the Fedex Service Guide, Service Guide Terms and Conditions will take precedence.
Failed:	A package, with article, that has failed all FedEx Standard Testing Procedures.
Pending:	A package, with article, that has been tested to all FedEx Standard Test Procedures. Confirmation of results is subject to customer inspection.

Comments and Packaging Recommendations*

* Our provision of advice, assistance or guidance on the appropriate packaging of shipment does not constitute acceptance of liability, unless such advice, assistance or guidance is in writing from the FedEx Packaging Design and Development department and expressly accepts liability in the event of a damaged shipment.

Photos / Drawings (if Applicable)

